APPLIED OVER BRICK ROADWAY

PROJECT NY 82-7


F-000S(39); M-000S(39)

CITY OF JAMESTOWN

CHAUTAUQUA COUNTY

EDWARD J. ZACK, MATERIALS ENGINEER
REGIONAL INVESTIGATOR

FINAL REPORT
JUNE, 1990




EXPERIMENTAL PROJECT REPORT

	EXPERIMENTAL PROJECT NO.		ION PROJ. NO.	LOCATION	
EXPERIMENTAL	STATE YEAR NUMBE	F-000S (Chautauqua	
	NY 8 2 0	$Z \square _{8} M-000S$	39)	County	
PROJECT	EVALUATION FUNDING		NEEP NO. PR	OPRIETARY FEATURE?	
		DEMONSTRATION		O YES	
	48 2 A CONSTRUCTION 4		49 51	ON EX	
	TITLE				
SHORT TITLE	Fabric In Asphaltic Overlays Applied Over Brick Roadway				
	DATE MO. YR. REPORTING				
THIS FORM	1 DINITIAL 2 DANNUAL 3 & FINAL				
	140 [0]0 [9]0 [144				
	KEY WORD 1		KEY WORD 2		
	Pavement Asphalt		0verlays		
KEY WORDS	KEY WORD 3		KEY WORD 4		
	Reflective Cracks		[21]		
	UNIQUE WORD PROPRIETARY FEATURE NAME [233] Non-Woven polypropylene [255]		UHE NAME		
	Date Work Plan Date Feature	Evaluation	h	Date Evaluation	
0110011011011	Approved: Constructed: MO. YR. MO.	YR. Scheduled Unti	Evaluation Extended Until YR. MO.	Terminated: YR. MO. YR.	
CHRONOLOGY	10-8209-	83 09-8		8 9	
	277 281	285	289	293	
	QUANTITY OF UNITS	UNITS		COST (Dollars, Cents)	
2747147 713	(Rounded to whole numbers)	1 LIN. FT. 5	-		
QUANTITY			LBS.		
AND COST	1 , , , 6, 4, 8, 0		JEACH 1	1 1 1 1 1 1 1 6 1 6	
71110 0001			LUMPSUM	1 1 10 0	
	297	305	306		
AVAILABLE	☑ CONSTRUCTION	PERFORMANCE	X FINAL		
EVALUATION REPORTS	315				
REFORTS	CONSTRUCTION PROBLEMS		PERFORMANCE		
	1 U NONE 2 STIGHT		2 Goo	ELLENT	
EVALUATION	3 MODERATE	SALES AND PARTY PARTY.		ISFACTORY	
Date of the second	4 SIGNIFICANT		4 🗆 MA		
	5 SEVERE		5 D UNS	SATISFACTORY	
	318		[319]		
	I ADOPTED AS PR	IMARY STD. 4 🖾	PENDING	(Explain in	
APPLICATION	2 PERMITTED ALT	ERNATIVE 5	REJECTED	Remarks if 3, 4, 5, or	
ALLEGATION	3 ADOPTED COND	ITIONALLY 6	NOT CONSTRUCTED	6 is checked)	
	320				
	a red or total				
THE PARTY AND PARTY	[321] After seven years, all test sections are continuing to provide				
	excellent performance. The fabric reinforced sections have				
	excellent performa	ince. The fabri	c reinforced s	ections have	
REMARKS	not performed any better than the non-fabric reinforced control				
sections.					
		NYSDOT		700	
FORM FHWA 1461	Charleton Charleton	Library			

(REV. 8-79)

50 Wolf Road, POD 34 Albany, New York 12232



FABRIC IN ASPHALT OVERLAYS APPLIED OVER BRICK ROADWAY

CITY OF JAMESTOWN

CHAUTAUQUA COUNTY

PROJECT NY 82-Ø7

F-000S(39); M-000S(39)

INTRODUCTION

Geotextiles have gained increasing recognition and acceptance for use as a deterrent to reflective cracking in asphalt concrete overlays. Many installations exist in connection with asphalt concrete overlays on portland cement or asphalt concrete pavements.

The subject experimental project provided an opportunity to install and monitor geotextile interlayer effectiveness with an asphalt concrete overlay on an existing brick pavement.

PROJECT

N.Y.S. Contract D250315 - Intersection Improvement, City of Jamestown, Chautauqua County, New York.

FA Project F-000s(39); M-000s(39); Experimental Project NY 82-07 (Portion of main project only).

Letting Date February 3, 1983; Experimental work completed various dates summer of 1983.

GENERAL

The construction contract provided for widening, repaving and signalization at various isolated intersections in the City of Jamestown to improve traffic operations and capacity. Also included were two short blocks (700 '+/- total) of brick pavement which were to be resurfaced for ride quality improvement. It was this two block length which was chosen for the experimental project.

All paving and resurfacing on this project specified the use of a geotextile membrane.

PROJECT NY 82-07 (Refer to map attachment "A")

General

A two-block (700' +/-) segment of 6th Street between Main Street and Washington Avenue in the City of Jamestown was chosen for the experimental work. This 32' wide brick pavement serves as a segment of the westbound portion of a two-way couple for N.Y.S. touring Rte. 394 through the City.

The original design typical section provided for brick pavement cleaning; tack coat (Item 407.0101*); variable depth machine-laid leveling course (Item 403.21*); 1 1/2" Asphalt Concrete Binder Course Type 3 (Item 403.13*) finished with a 1 1/2" Asphalt Concrete Top Course Type 7F (Item 403.19*). (See Typical Section Attachment "B").

The geotextile fabric was to be placed between the binder and top courses (Item 91410.51 - Non-Woven Polyproplene Membrane -See Attachment "C").

To provide for the study, the following modifications were made to the plan typical section:

- 1) As a Control section, the membrane was omitted on the south side of 6th Street between Cherry Street and Washington Avenue.
- 2) The membrane was placed directly on the brick pavement on the north side of 6th Street between Cherry Street and Washington Avenue. (Case A)
- 3) Placement of membrane between Cherry Street and Main Street was as called for in the design typical section, i.e., between binder and top courses. (Case B)
- 4) Although deemed desirable, the intended placement of membrane between the leveling course and binder course was abandoned due to complexities in scheduling, paving, traffic control and other project equipment demands.

*Item numbers refer to NYS Standard Specifications, January 2, 1981 and current addenda thereto

AND RESIDENCE OR IL PROPERTY OF TAXABLE

SUBBUSE .

A LE SERVICE DE LES DES LA CONTRACTOR DE LA CONTRACTOR DEL CONTRACTOR DE LA CONTRACTOR DE LA CONTRACTOR DEL CONTRACTOR DEL CONTRACTOR DE LA CONTRACTOR DEL CONTRAC

The state of the s

bee reduced the state of the st

to the gran typical movings. The fellowing sodifications and and actions to the

to resting on the case of the contract between there are

remarked dried out to directly beauty him of the contract of

The sand security of the sand security Street and the sand

to increase behavior out addressed breast from the contract and provided and the contract and provided and contract and co

that is Assumed the transfer phonestrant your against a resident

_Condition of Existing Pavement

The existing brick pavement was in general, sound but extremely irregular in surface profile both longitudinally and transversly. Variances on the order of 3/4" to 1 1/2" in 10' were not uncommon. Additionally, a relatively large area of concrete patch existed as a wearing course diagonally curb to curb approximately midway between Cherry Street and Washington Avenue.

After cleaning and brooming, the mortar joints between the bricks were found to be voided to an average depth of approximately 3/8". The brick surface was polished and extremely dense in appearance.

Materials

Geotextile Membrane - Fibretex AO as manufactured by Crown Zellerbach.

Asphalt Sealant (Contract Option) - Cationic Asphalt emulsion GR CRS-2 in accordance with N.Y.S.D.O.T. Item 702.4101*.

Equipment

As per Specification (see Attachment "C")

Weather

Little wind was evident and partly cloudy conditions prevailed. Air temperature was $7\emptyset$ degrees F. and rising with a relative humidity of 65%. The pavement was damp in the early morning due to overnight dew but dried off sufficiently to begin work by mid-morning.

Construction - Membrane on Brick Segment

In addition to an inordinate amount of hand brooming, especially around drop inlets, pavement irregularities, valve boxes, curb radii, etc. two passes of the power broom were required to clean the pavement sufficiently for emulsion application.

After some experimentations, an application rate of $\emptyset.22$ gal/sy of CRS-2 emulsion was determined to be the desired target value. This provided not only excellent fabric "retention", but also filled the voided mortar

*Item numbers refer to NYS Standard Specifications, January 2, 1981 and current addenda thereto

0 1

joints in the brick completely. Application temperature of the emulsion was as per the specification, 130 degrees F. Some minor hand spraying was necessary, particularly adjacent to the curbing and at the radius of intersections to adequately cover the surface.

Under the prevailing conditions, actual emulsion "break time" was 25 minutes.

The geotextile membrane was installed from a roll of material suspended on a 3" diameter pipe carrying frame attached to the front end of a 3/4 c.y. bucket loader. "Home built" for this project only, this system worked remarkably well and trouble free. The membrane was placed with a minimum of effort, broomed and rolled with a Buffalo-Springfield PSR-15 roller.

Due to the unevenness of the brick pavement surface however, it was impossible to avoid numerous wrinkles which had to be hand cut and patched together. Large amounts of hand cutting, fitting and placing were also necessary at the intersection radius areas.

After rolling of the membrane, the hot mix asphalt concrete leveling course (1" nominal depth) was placed over the membrane in the conventional manner. Mat temperature ranged between 285 degrees - 305 degrees F. The paver was a Barber-Greene SB-140 with electronic grade control. Compactive effort was by Rex 1100 vibratory roller.

<u>Construction - Membrane between Binder and Top Course Asphalt</u>


<u>Concrete</u>

All features were as above except:

- 1) The ideal target application rate of the CRS-2 emulsion was found to be $\emptyset.35$ gal/s.y.
- 2) The geotextile membrane placement was accomplished virtually wrinkle-free due to the smoothness of the newly laid asphalt concrete surface.


COMMENTS AND OBSERVATIONS

- 1) Considering that the operations, material and technique required were new to all concerned, the project in actuality went off quite well. As the project progressed, productivity increased and all operations tended to run increasingly smooth.
- 2) The placement of the membrane in a heavily trafficked, relatively narrow urban area short block is cumbersome and



tends to be extremely labor intensive. The contract bid price for geotextile membrane in place including sealant on this project was \$1.65 P.S.Y. Contractor has indicated that his actual cost was over \$5.00 P.S.Y. Such a cost, if actually required to be paid, would seem to dramatically affect any cost effectiveness of the installed system.

- 3) Wrinkles in the geotextile membrane were unavoidable on this project where the membrane was laid directly on the brick, due to the irregular nature of the brick pavement surface. All other factors being equal (including degree of reflective cracking-retardance), it would seem preferable to place the geotextile membrane on a smooth asphalt concrete surface, either leveler or binder course, or on cement concrete pavement. Where fabric was placed on newly paved asphalt concrete binder course, wrinkles were not a problem but tended to appear, if at all, at the longitudinal extremities of the fabric. They appeared to be a function of roll width as their prevalence was markedly reduced where narrower rolls were of necessity utilized.
- 4) Fibretex AO was well suited to the purpose on this project; it laid into the sealant well, showed excellent absorption, exhibited little or no "tracking" under construction traffic and adhered tenaciously to the underlying course.
- 5) It was found expeditious to begin placement of the geotextile membrane into the emulsions sealant at the first indication of "break", particularly where heavy amounts of hand work were required. Once the emulsion "break" began, it continued rapidly and if placement was not begun soon enough, areas resulted where the sealant became too hard for adequate absorption and bond by the membrane.
- 6) A leveling course asphalt concrete placement directly on brick was made immediately longitudinally adjacent to the segment where membrane was placed on the brick pavement. After compaction, the underlying brick "waffle" course was visible in shadow pattern in the area where no membrane was placed. No shadow pattern was visible in the membrane areas.
- 7) This project affords the opportunity to observe membrane-pavement-reflective cracking interactions in a number of placement conditions within the same contract; membrane on brick, membrane on binder over brick and membrane on existing asphalt concrete (over brick and portland cement concrete base). Upon completion, no visible signs of any differential behaviors or appearances amongst the various installations could be noted. No unusual problems other than noted above were encountered in the construction or behavior of any section. No slipping or sliding was evident in any situation.



A total 6,488 s.y. of geotextile membrane was installed on this project. Of this total, 2,774 s.y. was installed on the 6th Street portion, and of that total, 446 s.y. were placed directly on the brick pavement.

EVALUATION:

Project condition was monitored on an annual basis, over the past seven (7) years. Visual observations were noted and interim reports (FHWA-146) filed as required.

FINDINGS:

- The interim reviews conducted during 1984 indicated that no difference between Case A, B or Control sections was noted.
- 2. Additionally, no cracking of any type was noted.
- 3. The 1985 interim review indicated <u>no</u> difference between Case A, B. or Control sections.


However, a single longitudinal reflective crack developed along the Control section approximately 20' in length with a single transverse crack at each end, 6-8' in length projecting perpendicularly across into the Case A section. The configuration was that of an elongated "U" and actually mirrored or reflected a concrete patch in the underlying brick pavement.

The vertical face of the patch actually protruded approximately 1/2" above the adjacent brick, no transition leveler was used during the pavement preparation.

This heavy stress point reflective crack is plotted on the attached map (indicated in red).

No additional cracking of any type was noted at this time.

4. During the interim reviews of 1986 to the present, no additional cracking was noted and no difference between Case A, B or Control is evident.



CONCLUSIONS:


- 1. After almost seven (7) years of service, all sections are performing identically.
- 2. All sections are continuing to provide excellent performance.
- 3. The fabric reinforcement failed to make any significant improvement in preventing the advancement of reflection cracking in a brick pavement.
- 4. The fabric reinforced sections have <u>not</u> penformed any better than the non-fabric reinforced (control) sections.

RECOMMENDATIONS:

On the basis of this single installation, the additional costs incurred in the preparation and placement of fabric reinforcement have not been transmitted into an equivalent gain in service life.

Whether seven (7) years is a sufficient evaluation period is unknown and perhaps at some point in the future, a more definitive difference may be evident.

We therefore would recommend that the use of fabric reinforcement over brick pavement <u>not</u> be considered a general alternative to conventional overlay rehabilitation techniques.




ACKNOWLEDGEMENTS


Thanks are extended to personnel of the L. C. Whitford Co., Wellsville, New York for their cooperation in progressing the project. Additionally, S. Medley, C.E. I, Engineer-In Charge, and T. Krauza, T.C.I. III, provided invaluable assistance in data gathering and project field control. The study was conducted under the supervision of I. J. Pecnik, Associate Civil Engineer, now employed by the Strategic Highway Research Program.



ASPEL BELLEY 0 000 SIGNAL 57A. XPA 0+00 - OMIT NONWOVEN POLYPOPYLENE MEMBRANE - EXIST. CONCRETE PAV'T. PATCHING STA. XPA 0+02 LIMIT OF FABRIC ± (1) 4° 187 () A. () STATE OF THE PARTY (1) A 15 STA, XPA' 2+6: 200 D250315 - NY 82-07 F0005 (39) - M0005 (39) D THE 6th STREET OS. MAN O A MA PAVING LIMIT PAYING CASE & LASE B - FABRIC PLACED BETWEEN BINDER : TOP CASE A - FABIRIC PLACED DIRECTLY ON BRICK 4 6th St. ITEM 808 AND

ATTACK A





BETWEEN MAIN ST

ထ

WASHINGTON ST.

AHAGE B



AHACH C 10+3,

91410.51 - NONWOVEN POLYPROPYLENE MEMBRANE

DESCRIPTION

Under this Item, the Contractor shall supply and place a Nonwoven Polypropylene Membrane in accordance with these specifications at the locations shown on the plans or as directed by the Engineer.

MATERIALS

- 1. The Asphalt Sealant shall be applied to the existing road surface prior to application of the fabric. The Asphalt Sealant shall be an Emulsion or Asphalt Cement as directed by the Engineer or as shown on the plans.
 - a) Emulsion A cationic asphalt emulsion, grade CRS-2 meeting requirements of 702-4101 "Cationic Asphalt Emulsion (CRS-2)" of the N.Y.S.D.O.T. Standard Specification.
 - b) Asphalt Cement Asphalt cement shall be AC-5 meeting the requirements of Section 400, Bituminous Pavement, of the N.Y.S.D.O.T. Standard Specifications.
- 2. The Fabric shall be applied over the asphalt sealant and shall have the following properties:
 - a) Minimum Weight

3.6 oz./sq.yd.

b) Minimum Tensile Strength
(as determined in accordance
with A.S.T.M. Method
D-1682-64)

90 lbs.

c) Minimum elongation -atbreak (as determined in accordance with A.S.T.M. Method D-1682-64)

55%


d) Minimum Asphalt Retention

0.20 gals./sq.yd.

EQUIPMENT

The asphalt distributor shall be suitably metered and capable of spraying the asphalt sealant at the prescribed temperature and application rate. It shall be adjustable to give a uniform spray pattern over the entire width of application without dripping or skipping.

Hand spraying shall be kept to a minimum and limited to areas where a distributor cannot be used.



100

Mechanical fabric laydown equipment shall consist of a tractor unit capable of laying full rolls of fabric without excessive wrinkles and/or folds.

INSTALLATION PROCEDURES

1, Pavement Preparation

- a) The underlaying asphalt cement course shall be cleared of any dirt, dust and vegetation by either brooming or flushing with water before application or sealant.
- b) The asphalt cement course shall then be cleared of all sharp or angular protrusions.

2. Application of Sealant

The asphalt sealant shall be uniformly spray applied at the rate of 0.25 to 0.30 gallons per square yard. Within street intersections or other areas where vehicle speed is commonplace, the application rate shall be reduced by 20 percent. The rate of application may be adjusted based on observations or membrane manufacturer's recommendations as directed by the Engineer.

The temperature of the asphalt emulsion at the time of application shall be 130°F. If hot asphalt is applied, the temperature of the asphalt cement shall be between 250° and 350°F.

The width of application shall be fabric width plus 2 to 6 inches. Asphalt spills shall be cleaned from pavement surface to avoid flushing and possible fabric movement.

The asphalt emulsion shall then be allowed to cure prior to placement of the fabric. Typical emulsion cure times are shown below.

TYPICAL EMULSION CURE TIMES

Temperature	Dry	Humidity Moderate	Humid
€0°F	2 Hrs.	3 Hrs.	4 Hrs.
75 ⁰ F	1 Hr.	2 Hrs.	3 Hrs.
80°F	30 Min.	1 Hr.	2 Hrs.

Descort

Amenantial Tabeto Isydose squipming shall consist of a smelor out faving full rolls of fabric

PROPERTY OF PROPERTY AND PERSONS ASSESSED.

As Personal Properties

- of the underlaying aspinit communication by class of the distance of the distance of the stance of t
- beverts od neds limit estudo tommen slanges ods for

APPLICATION OF SOMERAL

The amphals sentant whall be uniformly apray applied at the rate of 0.30 to 0.30 gallons per equare yard. Which a news applied appeal a consequence intersections of other areas where vehicle reduced by 30 norcest. The rate of application may be adjusted based on observations or assistant menu-

to west ont the appeal to the appeal county believed to the time applied, the transmitted the applied the appeal to between the appeal county and the between

2 to 6 inches. Amphalt opille shall be cleaned from pavement sentlace to avoid flumbic and possible fabric movement.

To placement of the fabric. Typics Coulston ours times

equit anna Mark Malana

If hot asphalt cement is applied, the placement of the fabric shall follow immediately behind the application of the hot asphalt cement.

3. Application of Fabric

The fabric shall be placed into the asphalt sealant with a minimum of wrinkles by using the tractor powered unit.

Wrinkles severe enough to cause folds shall be slit and layed flat. The fabric shall be broomed from center outward, moving in the direction of laydown to establish uniform contact with sealant.

Transverse and longitudinal joints shall be made by overlapping the fabric 1 to 3 inches with additional sealant applied at a rate of 0.20 gal./sq.yd. to the joint as required and then broomed.

After fabric has been applied and broomed the fabric shall be rolled with a pneumatic roller.

In the event that the sealant bleeds through the fabric before the asphalt courses are placed, it may be necessary to blot the sealant by spreading sand or hot mix over the affected areas. This will prevent any tendency for construction equipment to pick up the fabric when driving over it.

METHOD OF MEASUREMENT

The measurement for payment for nonwoven polypropylene membrane shall be the number of square yards of membrane placed in accordance with the plans or as approved by the Engineer.

BASIS OF PAYMENT

The unit price bid per square yard shall include the cost of pavement preparation, cleaning, asphalt sealant, sealant application, fabric, fabric application and all materials, labor and equipment necessary to complete the work.

0280315 PHAMEN C 313

If hot asphalt coment to applied, the placement of the fabric obalt follow immediately behind the application of the not application

Application of Papric

The fauric shall be placed into the aspest sealest with with a minimum of wrinkles by using the tractor powered unit.

Wrinkles nevere enough to cause folds shall be slit and layed tiet. The fabric shall be broomed from center dutyerd, moving in the direction of laydows to setablish sortion onerset with sealant.

overlapping the fabric 1 to 3 inches with additional courfapping the fabric 1 to 3 inches with additional seasons applied at a rate of 0.20 gal/aq.yd. to the joint an required and then broomed.

After rebric has been applied and brocked the fabric

To the event that the sealant bleeds through the fabric before the usphalt courses are placed. It may be necessary to blot the scalant by spreading and or bot mix over the affected areas. This will prevent any tendency for construction equipment to pick up the fabric when driving

METHOD OF BEASURERENT

The resourcement for payment for nomeoven polypropylene nembrane shall be the number of square yards of sembrane placed to accordance with the place or as approved by the Segimen.

BASIS OF PAYMENT

The unit price bid per equare yard anall include the cost of payment property of the cost of application, deprice and all waterials, amount and softwarfels, labor and softwarfels, lab

01535 LRI